CITY OF BALTIMORE WET WI SMOKE AND DYED WA		Page 1 of	11
Sewershed: OUTFALL	Company: REI/DRAYCO	Date: 09/29/	2008
Test Type: SMOKE	Ground Condition: Dry: <b>X</b> Damp:_ Wet:_	Supervisor:	E.R.
Manhole ID: S51II_003MH	Test ID: S1039-003	Notifications Made:X	(Residents, Fire, 31
Field Sketch: (Show all manholes with n	umbers, blower placement location, sandb locations, defect locations and photo		building addresses and
003_OB03-01_	003_OB04-01	003_OB07-01	Blower #1 S51II_003M  251II_003M  251III_003M  251II_003M  25III_003M  25IIII_003M  25IIII_003M  25IIII_003M  25IIII_003M  25IIII_003M  25IIIII_003M  25IIII_003M  25IIII_003M  25IIII_003M  25IIIII_003M  25IIII_003M  25IIIII_003M  25IIIII_003M  25IIIII_003M  25IIIII_003M  25IIIII_003M  25IIIII_003M  25IIIII_003M  25IIIII_003M  25IIIIII_003M  25IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
Legend Primary and Abandoned Sewers Sewer Smoke Tested Sewer  Manhole Blower Location Observation Location Area Not to Smoke Test Flow Basin Boundary Outfall Sewershed Boundary Plat Boundary Parcels			

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM							Page 2 of 11					
	Sewershed: OUTFALL Company: REI/DRAYCO						Date: 09/29/2008					
Test Type: SMOKE Ground Condition:  Dry: X Damp:_ Wet:_						Supervisor: E.R.						
Manhole ID: S51II_003MH			Test ID: S1039-003									
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)												
Defect No.	Address	and it	Source Type	Locatio		Drair Area	nage	Severity		Photo Number		
	2624 E. FEDERAL ST		02	05	02	7 (100		03	S	1039-003_OB01-P01.jpg		
OB02	2634 E. FEDERAL ST		03	07	02	1		03	S	1039-003_OB02-P01.jpg		
OB03	2636 E. FEDERAL ST		03	07	02		1	03		1039-003_OB03-P01.jpg		
OB04	2704 E. FEDERAL ST		03	07	02	1		03		1039-003_OB04-P01.jpg		
	2714 E. FEDERAL ST		03	07	02	1		03		1039-003_OB05-P01.jpg		
	2716 E. FEDERAL ST		03	07	02	1		03		1039-003_OB06-P01.jpg		
	2720 E. FEDERAL ST		03	07	02	1		03		1039-003_OB07-P01.jpg		
	2728 E. FEDERAL ST		03	07	02	1		03		1039-003_OB08-P01.jpg		
OB09	2810 E. FEDERAL ST		03	07	02	1		03	5	1039-003_OB09-P01.jpg		
-												
									<u> </u>			
<u> </u>						1			-			
									-			
			OF	SERV <i>A</i>	ATION CC	DES						
	Source Type			Location			S	Sector		Severity		
	ain Sewer   10 MH Fra		Paved C		0 Non-Pa			Public	01	No Smoke		
	ervice Line 11 Storm		Asphalt		1 Field/W	oods/	02	Private	02	Trace		
		Paved C		2 Alley					Moderate			
						Golf Course			04	Major		
	rea Drain 14 Storm		Sidewal	к 1	4 Other		<u> </u>					
	wy. Drain 15 Excava		Curb	ront					-			
	air. Drain 16 Water ound. Drain 17 Tele. F		Yard - F Yard - B						-			
	dg. Interior 18 Other		Yard - S				-		<del> </del>			
00 DI	-gc.io.   10   Outor	11 00		.50					<u> </u>			

PAGE 3 of 11

## CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY **OUTFALL SEWERSHED BALTIMORE CITY PROJECT 1039** REI/DRAYCO

Unique Test ID: S1039-003 Date: 09/29/2008 Manhole ID: S51II\_003MH

Defect No: OB01 Supervisor: E.R. Basin: Outfall

Location: 2624 E. FEDERAL ST.

Source Type: 02 Service Line Sector: 02 Private

Location: 05 Sidewalk Severity: 03 Moderate Drainage Area: 4 ft<sup>2</sup>
Comments: Smoke is coming from the edge of the sidewalk closest to 2624 E. Federal St. along service line.

#### **SMOKE TEST PHOTOGRAPHS**



Photograph No: OB01-P01 Filename: S1039-003\_OB01-P01.jpg

PAGE 4 of 11

## CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY OUTFALL SEWERSHED BALTIMORE CITY PROJECT 1039 REI/DRAYCO

Unique Test ID: S1039-003 Date: 09/29/2008 Manhole ID: S51II\_003MH

Defect No: OB02 Supervisor: E.R. Basin: Outfall

Location: 2634 E. FEDERAL ST.

Source Type: 03 Cleanout Sector: 02 Private

Location: 07 Yard - Front Severity: 03 Moderate Drainage Area: 1 ft<sup>2</sup>

Comments: The above grade cleanout in front lawn has a broken cap.

#### **SMOKE TEST PHOTOGRAPHS**



Photograph No: OB02-P01 Filename: S1039-003\_OB02-P01.jpg

PAGE 5 of 11

## CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY OUTFALL SEWERSHED BALTIMORE CITY PROJECT 1039 REI/DRAYCO

Defect No: OB03 Supervisor: E.R. Basin: Outfall

Location: 2636 E. FEDERAL ST.

Source Type: 03 Cleanout Sector: 02 Private

Location: 07 Yard - Front Severity: 03 Moderate Drainage Area: 4 ft<sup>2</sup>

Comments: The below grade cleanout in the front lawn is missing a cap.

#### **SMOKE TEST PHOTOGRAPHS**



Photograph No: OB03-P01 Filename: S1039-003\_OB03-P01.jpg

PAGE 6 of 11

## CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY OUTFALL SEWERSHED BALTIMORE CITY PROJECT 1039 REI/DRAYCO

Unique Test ID: S1039-003 Date: 09/29/2008 Manhole ID: S51II\_003MH

Defect No: OB04 Supervisor: E.R. Basin: Outfall

Location: 2704 E. FEDERAL ST.

Source Type: 03 Cleanout Sector: 02 Private

Location: 07 Yard - Front Severity: 03 Moderate Drainage Area: 1 ft<sup>2</sup>

Comments: Above grade cleanout in front lawn has a broken cap.

#### **SMOKE TEST PHOTOGRAPHS**



Photograph No: OB04-P01 Filename: S1039-003\_OB04-P01.jpg

PAGE 7 of 11

## CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY OUTFALL SEWERSHED BALTIMORE CITY PROJECT 1039 REI/DRAYCO

Unique Test ID: S1039-003 Date: 09/29/2008 Manhole ID: S51II\_003MH

Defect No: OB05 Supervisor: E.R. Basin: Outfall

Location: 2714 E. FEDERAL ST.

Source Type: 03 Cleanout Sector: 02 Private

Location: 07 Yard - Front Severity: 03 Moderate Drainage Area: 1 ft<sup>2</sup>

Comments: Below grade cleanout in front lawn has a broken cap.

#### **SMOKE TEST PHOTOGRAPHS**



Photograph No: OB05-P01 Filename: S1039-003\_OB05-P01.jpg

PAGE 8 of 11

# CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY OUTFALL SEWERSHED BALTIMORE CITY PROJECT 1039 REI/DRAYCO

Unique Test ID: S1039-003 Date: 09/29/2008 Manhole ID: S51II\_003MH

Defect No: OB06 Supervisor: E.R. Basin: Outfall

Location: 2716 E. FEDERAL ST.

Source Type: 03 Cleanout Sector: 02 Private

Location: 07 Yard - Front Severity: 03 Moderate Drainage Area: 1 ft<sup>2</sup>

Comments: Below grade cleanout in front lawn has a broken cap.

#### **SMOKE TEST PHOTOGRAPHS**



Photograph No: OB06-P01 Filename: S1039-003\_OB06-P01.jpg

PAGE 9 of 11

## CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY OUTFALL SEWERSHED BALTIMORE CITY PROJECT 1039 REI/DRAYCO

Unique Test ID: S1039-003 Date: 09/29/2008 Manhole ID: S51II\_003MH

Defect No: OB07 Supervisor: E.R. Basin: Outfall

Location: 2720 E. FEDERAL ST.

Source Type: 03 Cleanout Sector: 02 Private

Location: 07 Yard - Front Severity: 03 Moderate Drainage Area: 1 ft<sup>2</sup>

Comments: Below grade cleanout in front lawn has a broken cap.

#### **SMOKE TEST PHOTOGRAPHS**



Photograph No: OB07-P01 Filename: S1039-003\_OB07-P01.jpg

PAGE 10 of 11

## CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY OUTFALL SEWERSHED BALTIMORE CITY PROJECT 1039 REI/DRAYCO

Unique Test ID: S1039-003 Date: 09/29/2008 Manhole ID: S51II\_003MH

Defect No: OB08 Supervisor: E.R. Basin: Outfall

Location: 2728 E. FEDERAL ST.

Source Type: 03 Cleanout Sector: 02 Private

Location: 07 Yard - Front Severity: 03 Moderate Drainage Area: 1 ft<sup>2</sup>

Comments: Above grade cleanout in front lawn has a broken cap.

#### **SMOKE TEST PHOTOGRAPHS**



Photograph No: OB08-P01 Filename: S1039-003\_OB08-P01.jpg

PAGE 11 of 11

## CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY OUTFALL SEWERSHED BALTIMORE CITY PROJECT 1039 REI/DRAYCO

Unique Test ID: S1039-003 Date: 09/29/2008 Manhole ID: S51II\_003MH

Defect No: OB09 Supervisor: E.R. Basin: Outfall

Location: 2810 E. FEDERAL ST.

Source Type: 03 Cleanout Sector: 02 Private

Location: 07 Yard - Front Severity: 03 Moderate Drainage Area: 1 ft<sup>2</sup>

Comments: At-grade cleanout in front lawn is missing a cap.

#### **SMOKE TEST PHOTOGRAPHS**



Photograph No: OB09-P01 Filename: S1039-003\_OB09-P01.jpg